

CASE STUDY

Pyplok™



INSTALLATION DATE:
January 2022

END USER:
Vale Malaysia

LINES SIZES AND MATERIAL:
1 1/4" SCH80 and 2" SCH80,
2205 Duplex Steel

SYSTEM MEDIUM:
5000 PSI Hydraulics

LOCATION:
Malaysia

SPECIAL COMMENTS OR NOTES:
Repair leaking welded flange joints with Duplex PYPLOK on
Stacker Reclaimer Unit.



