

# CASE STUDY



**MAERSK**

## INSTALLATION DATE:

August 15, 2017

## END USER:

Maersk Oil and Gas A/S

## LINES SIZES AND MATERIAL:

4" NPS Pipe, carbon steel

## LOCATION:

Tyra West Platform A in the North Sea

## SYSTEM MEDIUM:

Wellbore fluids

## SPECIAL COMMENTS OR NOTES:

Vent line repaired with 4" NPS PYPLOK carbon steel fitting. PYPLOK Technician arrived by helicopter and completed the repair within 2 hours.







